New York State Department of Environmental Conservation

Office of Environmental Quality, Region 4

1130 North Westcott Road, Schenectady, New York 12306-2014

Phone: (518) 357-2045 • Fax: (518) 357-2398

Website: www.dec.ny.gov



September 28, 2012

Steve Coladonato Honeywell International Inc. 6100 Philadelphia Pike Claymont, DE 19703

Re: Spill #9909741

Two Former Furon Sites

14 McCaffrey Street and 1 Liberty Street

Hoosick Falls, NY

Dear Mr. Coladonato:

Based on all the data submitted to date pertaining to the two above-referenced properties, this office is requiring no further action at this time and we consider this matter closed. Please be advised that residual chlorinated solvent contamination remains at both of these properties and this letter does not limit Honeywell International Inc.'s liability should unforeseen problems arise in the future as a result of this contamination.

I can be reached at 518-357-2399, if you have any questions. Thank you for your cooperation in this matter.

Sincerely,

Keith D. Goertz, P.E. Regional Spill Engineer.

Region IV

KDG:lg\letter.sp9909741.2012-09-28.NFA.doc

ec: Dan Forlastro, AMEC (<u>dan.forlastro@amec.com</u>)
Bob Cozzy, NYS DEC